

8. DIAGNOSTICS MESSAGES

MALFUN. CODE	DESCRIPTION	POSSIBLE CAUSES	VERIFICATIONS and SOLUTIONS
017	Invalid firmware detected on iDEA expansion board	iDEA expansion board not programmed correctly	Update the software. If the problem persists, replace the iDEA expansion board
019	Board communication fault on 485 Bus: iDEA expansion board	Module on 485 Bus not connected correctly Board faulty or not programmed	Check the module is correctly inserted and positioned on the relative connector Check the status LED is working properly (normally flashing on the module) Update the software. If the problem persists: Replace module on 485 Bus Replace iDEA CPU
020	Power supply overcurrent alarm on USB port	USB-port current- consumption too high	 Check the status of the USB port and its connections in order to identify possible causes of excessive consumption (e.g. short-circuit) Once the cause of the malfunction is fixed the USB port should restore itself automatically and return to normal operation. If the problem persists, replace the CPU board
(x)21	Group boiler pressure sensor x out of range (x = 1, 2, 3, 4) Note: Group 1 is to the far left.	Sensor faulty Board faulty	Check the wiring Replace the sensor Replace the board
024	Insufficient clock battery voltage, or another fault (e.g. clock "jammed")	Contacts oxidised.Dead battery.Clock blocked.	Clean the contacts on the battery. Measure the voltage of the battery (3 V DC) and, if necessary, replace it. If the battery is OK try, with the machine turned off, to remove it from the board and wait 2-3 minutes. Then reinsert the battery and check that the clock is working properly.
(x)30	Restart on the button pad or group display (x = 1, 2, 3, 4, 5) Note: Group 1 is to the far left. 530 = services		•If the fault persists, replace the board.
051	Boiler temperature sensor outside range	Sensor failure Card failure	Check cabling Replace the sensor Replace the card
(x)51	Group boiler temperature sensor x out of range (x = 1, 2, 3, 4) Note: Group 1 is to the far left.	Thermocuple disconnected Sensor failure	Check cabling Replace the sensor



(x)52	Group x boiler heating timeout - 20 minutes (x = 1, 2, 3, 4) Note: group 1 is the one on the far left. 0 = boiler	 The group x boiler safety thermostat has been triggered The resistance is interrupted (cabling defect) 	 Check if the safety thermostat of the group x boiler has been triggered, and reset it if necessary Check if there are interruptions or detached fastons on the cabling Check that the group x boiler resistance is not interrupted and replace it if necessary
(x)53	Steam thermocouple out of range RH = 053; LH = 153	Thermocuple disconnected Wrong configuration during standard data insertion	 Enter in the programming mode and insert the correct standard data Check connections Replace the steam temperature probe
058	Boiler overpressure alarm	Resistanc alwayspowered Temperature sensor out of range.	Check cabling Replace the sensor
059	Boiler: Refill timeout	No waterRefill EV failureWiring interruptedCard failure	Check water is supplied from the main line Replace the refill EV Check cabling Replace the card
060	Boiler-level signal errors.	Electrical fault Leakage to earth	Check wiring Check, by activating the components individually on the manual control panel, that the level signal does not show any anomalies (%)
062	Coffees dispensed for MM1 with flow under the limit (3 consecutive coffees dispensed).	 Coffee filter blocked Coffee type changed Qref calibration wrong Grind too fine, excessive dose ground. 	 Wash the group Clean/replace the coffee filter Use a coarser grind Calibrate the machine correctly on the basis of the coffee/recipe.
063	Coffees dispensed referred to MM1 with flow over the limit (3 consecutive coffees dispensed).	Coffee type changed Qref calibration wrong Grinding too coarse Grinder/dispenser blocked, insufficient dose of ground coffee.	 Check that there are no external elements in the grinders Check that the measure grinder is working (pick-up current and fuses) Use a finer grind Calibrate the machine correctly on the basis of the coffee/recipe.
064	Coffees dispensed referred to MM2 with flow under the limit (3 consecutive coffees dispensed).	 Coffee filter blocked Coffee type changed Qref calibration wrong Grind too fine, excessive dose ground. 	 Wash the group Clean/replace the coffee filter Use a coarser grind Calibrate the machine correctly on the basis of the coffee/recipe.
065	Coffees dispensed referred to MM2 with flow over the limit (3 consecutive coffees dispensed).	 Coffee type changed Qref calibration wrong Grinding too coarse Grinder/dispenser blocked, insufficient dose of ground coffee. 	 Check that there are no external elements in the grinders Check that the measure grinder is working (pick-up current and fuses) Use a finer grind Calibrate the machine correctly on the basis of the coffee/recipe.



(x)66	Coffee water dose fault during dispensing (recipe test or self-learning). (x = 1, 2, 3, 4) Note: Group 1 is to the far left.	Clogged hydraulic circuit Faulty volumetric doser	 Check water is supplied from the main line. Check there are no fitting obstructions or leakage. Check flowmeter electrical connections. Replace the broken flowmeter. Replace the broken board.
(x)67	Fault on group volumetric measuring device during coffee washing (x = 1, 2, 3, 4) Note: Group 1 is to the far left.	Clogged hydraulic circuit. Faulty volumetric doser	 Check water is supplied from the main line. Check there are no fitting obstructions or leakage. Check flowmeter electrical connections. Replace the broken flowmeter. Replace the broken board.
(x)70	Measure-grinder adjustment: Bluetooth set up by the technician. (x = 1, 2) MM1 = 170; MM2 = 270		Event only archived and not displayed on the display during normal machine operation.
(x)82	Button pad reset via CPU board owing to repeated communication problems. $(x = 0, 2)$		Check the insulation Check the wiring and connections
(x)83	Exclusion of group button pad from I2C Bus communication (x = 1, 2, 3, 4) Note: Group 1 is to the far left. (083=water button pad, 583 steam button pad, 683 TS board, 783 RGB light module)	 Incorrect keyboard configuration (if applicable). Wiring interrupted Card failure. 	 Check that the dip switches are correctly configured on the key board (if applicable). Check cabling Replace key board.
(x)85	Bluetooth communication error (x = 1, 2) MM1 = 185; MM2 = 285	Incorrect association with measure grinder.Measure grinder turned off.	Turn on the grinder.Repeat device association.
(x)87	Calibration fault on group touchscreen (x = 1, 2, 3, 4) Note: Group 1 is to the far left.		Calibrate the touchscreen
092	Request water softener resin regeneration.		Softener maintenance.
093	Request replacement water filter		Replace the water-softner filter.
096	Maintenance needed)		The machine has displayed the message to warn the user that maintenance must be performed. Carry out maintenance operations.
097	Reset standard password	Action desired by the user by entering the special code (applicable only for machines with TFT display).	



098	Historical malfunctions and wash 1 reset	Initialisation malfunction history (and washing history for machines without TFT display)	Event only archived and not displayed on the display during normal machine operation.
099	Default data input.		